

Release Notes
switchUp 24+2R
Firmware Revision v2.0.1
Release Date: 2003 August 20

Features Added

- None.

Features Changed

- Resetting the switch to factory defaults does not change the local MAC address.
- Upgraded the micro code to the latest version.

Hardware/Software Dependencies

- Please note that when a switch has been upgraded to v2.0.0, down grading to v1.x.x requires a different upload sequence of the image. The sequence is sw, boot, dbg, and cfg.

Fixed Issues

- Zilla# 3253 - 24+2 ESW: HOLDPHY_RST is tri-stated at boot

Known Issues

- Excessive traffic, such as in the case of a loop, excessive ARPs, etc., can cause interference with input to the serial console.