

**Release Notes**  
**CCPUcclb Library**  
**Firmware Revision v2.1.6**  
**Release Date: 2003 August 27**

---

***Features Added***

- Implemented the ability on CCNalm alarm panels to be reset via the CCNlib API command ccnxSetResetState.
- Added ccnxGetRlyOverride and ccnxSetRlyOverride APIs to get and set, respectively, the relay override setting on CCN\_MA2 alarm panels.

***Features Changed***

- No features changed

***Known Issues***

- Starting a CCNlib application program while a NetCCN image download over CCPUnet is in progress will cause that image download to terminate.

***Fixed Issues***

- ccnlog now reports CCNfru disk faults correctly.
- Fixed incorrect fault bit definitions for CCNalm alarm panels in sn\_ccnmalm.h header file.